

CHIRP - Bug # 3163

Status:	Closed	Priority:	Normal
Author:	Steve Fritts	Category:	
Created:	01/13/2016	Assignee:	
Updated:	04/23/2020	Due date:	
Chirp Version:	daily		
Model affected:	Yaesu FT-1900/FT-2900/FT-8800		
Platform:	Windows		
Subject:	Yaesu FT-1900/FT-2900/FT-8800 problem		
Description			
<p>I can not get the Yaesu 1900. 2900 or the 8800 to program. When I go in to clone mode and try to send or rec I get an error-"Can't read header". Nothingg I do seems to work. Any idea as to what I may be doing wrong? I am using an FTDI cable and the latest version of Chirp.</p> <p>Thank you and 73</p> <p>Steve Fritts W4YJ</p>			

History

#1 - 01/23/2020 06:44 pm - Bernhard Hailer

- Subject changed from yaesu problem to Yaesu FT-1900/FT-2900/FT-8800 problem
- Status changed from New to Feedback
- Target version set to chirp-daily
- Model affected changed from yaesu to Yaesu FT-1900/FT-2900/FT-8800

Could you eventually resolve the issue? This sounds like you were using a bad cable.
Please try again and attach a debug log as described in the Wiki: [\[\[How To Report Issues\]\]](#).

#2 - 04/23/2020 05:11 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.