

CHIRP - Bug # 3567

Status:	Closed	Priority:	Normal
Author:	Mitch Grant	Category:	
Created:	04/13/2016	Assignee:	
Updated:	04/15/2020	Due date:	
Chirp Version:	daily		
Model affected:	Yaesu FT-1900		
Platform:	Windows		
Subject:	FT1900 Failed to read header		
Description			
<p>Hello.</p> <p>I see other bug reports having about the same problem I'm having. I'm using the latest Chirp on a Windows 7 PC. I also installed the latest on my Ubuntu PC. I am using a Valley Enterprise cable RPC-YM6-UF. Both computers report the same error. Chirp works fine on my Alinco and Baofeng with cables from Valley. Both computers have the latest updates. Any ideas on what else to try. I'll attach the log file from the Windows 7 PC.</p> <p>Thank You Mitch</p>			
Related issues:			
related to Bug # 3143: Yaesu Ft-1900 Failed to read header		Closed	01/07/2016

History

#1 - 04/14/2016 07:55 am - Daniel Clerc

Hi Mitch!

Sorry, for insisting on this: are you sure that the cable is working and that the connection is fine? From the debug.log it looks like there was no proper connection. Can please double-check and send an updated debug.log?

Thanks,

Daniel

#2 - 04/16/2016 06:33 am - Mitch Grant

Thank you very much Dan. It's a brand new cable but there could be a problem with it. It'll have to find a way to test the cable or find another radio to test it on. As the software works on my other radios I'll assume the problem is on my end and nothing to do with your excellent program. Please mark this closed. As soon as I determine the problem, I'll let you know in case it may be of help to others.

Thanks again

Mitch

KD8ZXU

#3 - 04/15/2020 03:03 pm - Bernhard Hailer

- Status changed from New to Closed
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Yaesu FT-1900

Duplicates #3143. Please follow and post there. Thanks!

Files

debug.log	17.1 kB	04/13/2016	Mitch Grant
-----------	---------	------------	-------------