

## CHIRP - Bug # 4569

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Pete Ed	<b>Category:</b>	
<b>Created:</b>	02/28/2017	<b>Assignee:</b>	
<b>Updated:</b>	12/17/2019	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	GT-5TP		
<b>Platform:</b>	All		
<b>Subject:</b>	Baofeng GT-5TP		
<b>Description</b>			
<p>G'day Team ... Thank you for your excellent software.</p> <p>Just some "Feedback" ...</p> <p>I purchased two "Baofeng GT-5TP" radios last week, and they have different firmware to each other.</p> <p>1st one has FW: N82301 ... this one will not respond to the latest build of CHIRP (20170217) ... I keep getting either: "incorrect radio" or "radio does not respond" (messages are from memory so they may be a little different to actual) ... this one (FW: N82301) will respond to software from "baofengtech.com" (BaoFeng UV-82HP VIP Programming Software) ... programmed successfully :-)</p> <p>2nd one has FW: N82303 ... this one works fine with the latest build of CHIRP (20170217) and programed successfully , so, thank you again "CHIRP Team"!!!</p> <p>It seems that the N82301 FW has an issue with CHIRP (20170217), as the radio is programmable via the "other" software.</p> <p>Cheers ... Pete</p>			
<b>Related issues:</b>			
duplicated by New Model # 4435: Baofeng GT-5TP		<b>Closed</b>	<b>01/21/2017</b>
duplicated by New Model # 4723: Baofeng GT-5TP		<b>Closed</b>	<b>04/12/2017</b>

### History

#### #1 - 02/28/2017 05:27 pm - Jim Unroe

- Status changed from New to Feedback

CHIRP should detect the N82301 firmware version. It just looks for the "N82" part to recognize the radio. Please include the [debug.log](#) file.

Jim KC9HI

#### #2 - 02/28/2017 11:46 pm - Pete Ed

- File CHIRP\_debug\_01-03-2017.log added

G'day Jim.

Thanks for your reply mate.

I have replicated the situation. First using the "UV-82HP" radio selection, as indicated that should be used at the Chirp website. Error was something

like "Wrong Radio".

Next, I tried the "UV-5R" radio selection, and that failed also (I read somewhere that the UV-5R worked for some one). Error was something like "Radio did not respond".

Log file attached.

Cheers ... Pete

**#3 - 03/02/2017 03:20 pm - Jim Unroe**

Thanks for the debug.log file. CHIRP doesn't recognize your radio because it is not reporting a valid firmware version.

```
2017-03-01 18:26:57,140] chirp.drivers.uv5r - INFO: Radio Version is '\xff\xff\xff\xff\xff\xff\xff\xff\xff\xff\xff'
```

Is it an "official" UV-82HP purchased from Baofeng Tech or is it a variant purchased from someone else?

Jim KC9HI

**#4 - 03/02/2017 03:21 pm - Jim Unroe**

Never mind. Your radios are GT-5TP models that Baofeng Tech does not offer.

Jim

**#5 - 03/02/2017 03:58 pm - Pete Ed**

Thanks for your response Jim.

Is there any way of working around the "not reporting a valid firmware version" issue for this radio that I could do, maybe a config file that I can edit?

If not, not a problem, as I can use the "other" software - sadly, it is not as flexible as your "CHIRP" ;-)

Cheers ... Pete

**#6 - 03/24/2017 01:35 am - Julian Crisp**

Afternoon lads. I have a Baofeng GT-5TP (firmware N82301) with an identical issue. Keeps telling me that the radio didn't respond.

**#7 - 03/26/2017 06:51 pm - Jim Unroe**

The solution for this issue is being addressed [here](#)

Jim KC9HI

**#8 - 03/26/2017 07:21 pm - Julian Crisp**

Didn't work for me.. "Radio did not respond" again

**#9 - 03/27/2017 02:47 am - Jim Unroe**

Julian,

Do you have a working programming cable? Where is your debug.log file?

Jim KC9HI

**#10 - 03/27/2017 04:00 am - Julian Crisp**

- *File debug.log added*

The drivers installed for the cable so I assume it works. It shows up as COM3 in device manager. Debug.log attached.

**#11 - 03/27/2017 04:39 am - Jim Unroe**

You can't assume that if you are running Windows and a programming cable with a Prolific chip. Look in Device Manager. If it shows a Prolific chip on the Driver page, then the device driver version must be v3.3.2.105 or lower (v3.2.0.0 recommended) or it won't work.

Jim

**#12 - 03/27/2017 04:47 am - Julian Crisp**

Its version 3.8.12.0. How do I down grade?

**#13 - 03/27/2017 04:52 am - Julian Crisp**

Julian Crisp wrote:

| *Its version 3.8.12.0. Just down grading now*

**#14 - 03/27/2017 05:03 am - Julian Crisp**

Down graded to driver to 3.2.0.0, loaded the module that you linked above, selected the radio that you had listed in that post also. Still getting "Radio did not respond"

**#15 - 03/27/2017 06:26 am - Jim Unroe**

I need the debug.log from the 3.2.0.0 driver. This sounds like a cable not fully connected to the radio issue.

Jim

**#16 - 03/27/2017 07:52 am - Jim Unroe**

Julian,

Does the factory software work? If yes, let me know where it is available from.

Jim

**#17 - 03/27/2017 05:58 pm - Julian Crisp**

There was no factory software. Debug attached. Going to try a different cable in a hour or so. Will let you know if it works.

**#18 - 03/27/2017 06:04 pm - Julian Crisp**

- *File debug.log added*

Last one didn't work. Attached below

**#19 - 03/28/2017 01:27 pm - Jim Unroe**

Your radio does not respond. There is either a cable issue or your radio responds to a different "magic" code to initiate cloning. My guess is that it is a cabling issue. CHIRP can't solve that.

If it is because the radio responds to a different "magic" code, that magic code can only be determined from the factory software.

Do you have a GT-5TP like that of Ed (the person that opened this issue)? I just did some quick research, the GT-5TP is just a UV-82HP in different case. So it definitely responds to a different "magic". You both should be choosing UV-82HP (not BF-F8HP).

From the Supported Models list on the CHIRP home/wiki page:

- UV-82HP/82DX/82HX (3 power levels)  
*Also includes the GT-5TP*

Jim

**#20 - 03/28/2017 03:25 pm - Pete Ed**

G'day Jim.

I was choosing the UV-82HP (not BF-F8HP) setting with my GT-5TP (FW: N82301). I did have success with the second GT-5TP that I purchased, as I previously reported, and it has firmware N82303, so it must be an issue with the N82301 firmware.

Sadly, my GT-5TP with FW: N82301 has stopped working so I will no longer be able to give feedback with that firmware.

Cheers ... Pete

**#21 - 03/28/2017 03:33 pm - Jim Unroe**

Pete,

Yes. I knew you were selecting the correct model. Based on the debug.log that he supplied, it was Julian that was selecting the wrong model. Sorry for the confusion.

Thanks for the feedback. After I receive a few more reports of success, I will try to get a patch submitted.

Jim

**#22 - 03/28/2017 08:17 pm - Julian Crisp**

Tried a different cable yesterday, same thing, "radio did not respond". Are you able to send me a simple (i'm new to this) step by step guide of how to do this. From Installing to it hopefully working. I will uninstall and delete all CHIRP files now and reinstall so I have a fresh place to start. I'm pretty new to this so the simpler the better. My radio is the Baofeng GT-5TP with firmware N82301 just to confirm. Cheers.

**#23 - 03/29/2017 03:31 pm - Jim Unroe**

Julian,

What kind of programming cable did you get. A generic cable or the better one based on an FTDI chip.

If it a generic cable with Prolific chip, you must downgrade the driver as described in [this guide](#)

Jim

**#24 - 03/29/2017 04:18 pm - Julian Crisp**

- *File Device Manager.JPG added*

I have a generic cable. I'm on version 3.2.0.0. See screen shot attached.

**#25 - 03/29/2017 04:50 pm - Jim Unroe**

Julian,

The only other thing I can suggest right now would be to make sure the plug is fully inserted. On the GT-3 there is a ridge that runs around the socket well that can interfere and the plug sometimes needs trimmed to allow it to go in all the way. I don't know about the GT-5 radios. See [Radio did not respond](#) on the miklor website.

**#26 - 03/29/2017 05:37 pm - Pete Ed**

Hi Julian.

Have you tried to use the factory software that I mentioned in my first post? It worked OK for my GT-5TP that had the N82301 firmware.

Get the software from "baofengtech.com" in the download section. The software name is "BaoFeng UV-82HP VIP Programming Software". It is not as good as CHIRP, but it will at least let you know whether your radio's programming cable is working or not.

Cheers ... Pete

**#27 - 12/17/2019 12:25 pm - Jim Unroe**

- Status changed from Feedback to Resolved
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Platform changed from Windows to All

related to #4445

**#28 - 12/17/2019 12:25 pm - Jim Unroe**

- Status changed from Resolved to Closed

**Files**

---

CHIRP_debug_01-03-2017.log	23.1 kB	02/28/2017	Pete Ed
debug.log	22.8 kB	03/27/2017	Julian Crisp
debug.log	32.2 kB	03/27/2017	Julian Crisp
Device Manager.JPG	85.3 kB	03/29/2017	Julian Crisp