

## CHIRP - Bug # 6089

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	William J Dieringer	<b>Category:</b>	
<b>Created:</b>	09/06/2018	<b>Assignee:</b>	
<b>Updated:</b>	09/13/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Yaesu FTM-3200		
<b>Platform:</b>	Windows		
<b>Subject:</b>	FTM-3200 Checksum Failed [064A-06C8 (@06C9)]		
<b>Description</b>			
Using latest build with Windows 10. Receiving this error while "Reading from Radio". Progress bar makes it all the way to completion then the error pops up.			

### History

#### #1 - 09/06/2018 12:15 pm - William J Dieringer

Using RT-Systems cable.

#### #2 - 05/10/2020 07:20 pm - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily

Have you been able to resolve this on your own since you submitted this?

Have you tried with a recent version since you submitted this?

This could be a cable issue. Please refer to these Wiki articles:

[[CableGuide]]

[[CableGuide FTDI OEM Cables]]

If there's no solution to be found in any of them, please read: [[How To Report Issues]] and provide a debug log. Thank you!

Windows: If you are using a generic cable with a Prolific chip, you will very likely need to downgrade your driver to version 3.2.0.0.

It can be found at [http://www.miklor.com/COM/UV\\_Drivers.php](http://www.miklor.com/COM/UV_Drivers.php)

#### #3 - 09/13/2020 04:30 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.