

CHIRP - Bug # 6513

Status:	Closed	Priority:	High
Author:	Darren Brown	Category:	
Created:	03/01/2019	Assignee:	Jim Unroe
Updated:	02/11/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng BF-T1 and UVB6		
Platform:	All		
Subject:	Baofeng UVB6 and BF-T1		
Description			
<p>Latest build refuses to program 6.25khz and 12.5 khz steps on these two radio models.</p> <p>It will download and re write but it won't let me enter any new frequencies without the error messages about 6.25khz or 12.5 khz steps respectively.</p> <p>I tried the BF-T1 yesterday with yesterday's release and then the UVB6 with today's release...same issues.</p> <p>Help!</p>			

Associated revisions

Revision 3187:6eb12cbd259c - 03/03/2019 09:46 pm - Jim Unroe

[BF-T1] fix valid_tuning_steps list. #6513

History

#1 - 03/03/2019 01:01 pm - Jim Unroe

- Status changed from New to In Progress
- Assignee set to Jim Unroe
- Platform changed from Windows to All

The UV-B6 was addressed with bug #6543. I will be correcting the BF-T1 shortly.

Jim KC9HI

#2 - 03/03/2019 01:31 pm - Darren Brown

Jim Unroe wrote:

The UV-B6 was addressed with bug #6543. I will be correcting the BF-T1 shortly.

Jim KC9HI

Thankyou very much, Jim ! :-)

#3 - 02/11/2020 08:30 pm - Jim Unroe

- *Status changed from In Progress to Closed*

- *% Done changed from 0 to 100*

Resolved.

Jim KC9HI