

CHIRP - Bug # 7383

Status:	Closed	Priority:	Normal
Author:	Brandon Lee	Category:	
Created:	11/28/2019	Assignee:	
Updated:	02/18/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-82		
Platform:	Windows		
Subject:	Baofeng UV-82 not recognized		
Description	Received new Model:UV82, wanting to program channels with chirp. USB cable working with factory software (able to adjust settings). Connecting to chirp causing error with Model selected. Debug info shows issue with the 'magic' string.		

History

#1 - 11/29/2019 08:01 pm - Brandon Lee

Cable is the "Name brand" Baofeng cable, when plugged in and setup it shows up as the CH340 cable. Trying to use the 3.2.0.0 drivers is no avail. If I set CHIRP to UV82 I get Incorrect 'Model' Selected when trying to download. If i try and set is at UV-5R I get a "Radio did not respond" Error. UV-82III and UV-82WP "Error reading data from radio: not the amount of data we wanted"

#2 - 11/29/2019 08:18 pm - Brandon Lee

Forgot: Firmware version shows as FC82V01

#3 - 12/01/2019 01:07 am - Brandon Lee

After reviewing old bug issues and logs reported, looks like it may be a "new" firmware version? Not certain how to update this.

#4 - 12/03/2019 10:04 am - Jim Unroe

- Status changed from New to Feedback

Brandon,

I submitted a patch a couple of weeks ago to fix this. I just discovered that I made a mistake. I will be submitting another patch soon that should "fix" the issue.

Jim KC9HI

#5 - 12/03/2019 11:04 am - Jim Unroe

Patch submitted and accepted. The next daily build should work.

Jim KC9HI

#6 - 02/18/2020 06:24 pm - Bernhard Hailer

- Subject changed from UV82 - FCC Version? to Baofeng UV-82 not recognized
- Status changed from Feedback to Closed
- Model affected changed from (All models) to Baofeng UV-82

This should be complete.

Files

debug.log	24.8 kB	11/28/2019	Brandon Lee
-----------	---------	------------	-------------