

## CHIRP - Bug # 8771

<b>Status:</b>	New	<b>Priority:</b>	Normal
<b>Author:</b>	Bernhard Hailer	<b>Category:</b>	
<b>Created:</b>	01/31/2021	<b>Assignee:</b>	
<b>Updated:</b>	01/31/2021	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Icom IC-7100		
<b>Platform:</b>	All		
<b>Subject:</b>	Add further instructions for Icom IC-7100		
<b>Description</b>	<p>Issue #8707 suggests that adding instructions to use "RESET ALL" on the IC-7100 will resolve download issues, should they arise. Such issues appear to happen when the user switches to another cable (e.g. from RTSystems to BlueMax49ers).</p> <p>This is a request to add ths instruction "If connecting to the radio consistently fails, please perform a 'RESET ALL' on your IC-7100."</p>		
<b>Related issues:</b>	related to Bug # 8707: Failure to Write Memory IC-7100 Live-Mode Radio <b>Closed</b> <b>01/20/2021</b>		

### History

---