

CHIRP - Bug # 10020

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	09/01/2022	Assignee:	Jim Unroe
Updated:	09/09/2022	Due date:	
Chirp Version:	daily		
Model affected:	RT21 and others		
Platform:	All		
Subject:	Driver Maintenance: retevis_rt21.py		
Description			
The implementation of the <code>_skipflags</code> variable is incomplete. It can cause issues when additional models are added to this driver.			
Jim KC9HI			

Associated revisions

Revision 3737:5665300a504d - 09/08/2022 11:40 pm - Jim Unroe

Driver Maintenance: retevis_rt21.py (`_skipflags`)

This patch completes the `_skipflags` implementation.

Retevis RB17A, RB26, RT21 and RT76

Fixes #10020

History

#1 - 09/01/2022 02:04 am - Jim Unroe

- Status changed from *In Progress* to *Resolved*

- % Done changed from 0 to 100

A patch has been submitted. Support will be in the next CHIRP daily build following acceptance.

Jim KC9HI

#2 - 09/09/2022 12:30 am - Anonymous

- Status changed from *Resolved* to *Closed*

Applied in changeset commit:5665300a504d.