

CHIRP - Bug # 1189

Status:	Closed	Priority:	Normal
Author:	Don Schryver	Category:	
Created:	10/24/2013	Assignee:	
Updated:	04/28/2020	Due date:	
Chirp Version:	daily		
Model affected:	Anytone AT-5888UV		
Platform:	Windows		
Subject:	Anytone AT-5888UV Read Error		
Description			
<p>Just installed the daily version 20131022 and ran into an issue with the Anytone in that when reading the radio it seems to read each block fine and then produces an error "Short read from radio". This is on WXP SP3 with the C++ 2008 SP2 installed. "Clone 80" appears on the radio display when this occurs and remains until radio is power cycled.</p>			

History

#1 - 02/07/2020 12:51 pm - Bernhard Hailer

- Subject changed from Anytone 5888UV Read Error to Anytone AT-5888UV Read Error
- Status changed from New to Feedback
- Priority changed from Urgent to Normal
- Target version set to chirp-daily
- Model affected changed from Anytone 5888UV to Anytone AT-5888UV

Have you been able to resolve this on your own since you submitted this?

If you haven't, and if you're still having this issue, please refer to the Wiki [\[\[How To Report Issues\]\]](#), and provide a debug log. Thanks!

#2 - 04/28/2020 10:07 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.