

CHIRP - Bug # 1437

Status:	Closed	Priority:	Normal
Author:	Garrett Dow	Category:	
Created:	02/08/2014	Assignee:	
Updated:	02/23/2020	Due date:	
Chirp Version:	daily		
Model affected:	(All models)		
Platform:	Windows		
Subject:	tpe exports		
Description			
<p>I am using the latest version of TravelPlus (16.0) and the CHIRP daily build of 20140121 and get an error when importing channels that add an odd split or are simplex. This is extremely common on 6-meters as the ARRL lists the input freqs for all 6-meter frequencies in the input frequency field. Typically, the offset direction is recorded there (+,-). But, When a repeater is simplex or odd split, the frequency is shown. CHIRP is not able to handle this and displays an error.</p>			

History

#1 - 02/10/2014 06:27 pm - Jens Jensen

Hi Garrett,

please ensure you are using latest chirp daily, and attach a debug.log

http://chirp.danplanet.com/projects/chirp/wiki/How_To_Report_Issues#Getting-your-debug-log

#2 - 02/10/2014 06:27 pm - Jens Jensen

please also include the .tpe file you are trying to import

#3 - 02/23/2020 05:42 pm - Bernhard Hailer

- Status changed from New to Closed
- Assignee deleted (Tom Hayward)
- Target version set to chirp-daily
- Chirp Version changed from 0.3.0 to daily

No more feedback by submitter.