

CHIRP - Bug # 1619

Status:	New	Priority:	Normal
Author:	Robert Newton	Category:	
Created:	05/07/2014	Assignee:	
Updated:	05/07/2014	Due date:	
Chirp Version:	0.4.0		
Model affected:	(All models)		
Platform:	Windows		
Subject:	FT8800 Banks no programming on RH side		
Description			
<p>Using Chirp 0.4.0, trying to load bank selections for the RH side VFO and not the left. Save .img file and re-open it populates the LH side .img file as the RH side (bank-wise).</p> <p>Started with a clean sheet with 6 frequencies on LH side and 7 frequencies on the RH side. Go to banks(RH) and select which frequencies to desired banks. Go to banks(LH) and NO banks are selected. UPLOAD [Clean Slate UL01] Radio does not recognize the banks on either LH or RH side. Close out [Clean Slate UL01] File. Re-open [Clean Slate UL01] file. Banks no longer selected in sheets.</p> <p>DOWNLOAD [Clean Slate DL01] No banks selected in sheet.</p> <p>Copied [Clean Slate UL01] to [Clean Slate UL02] Go to banks(LH) and select which frequencies to desired banks. Go to banks(RH) and NO banks are selected. UPLOAD [Clean Slate UL02] Radio LH side matched [Clean Slate 02]. Radio RH side had no banks.</p> <p>Cannot seem to use Chirp to program banks on RH side VFO.</p>			

History

Files			
Clean Slate UL01.img	21.7 kB	05/07/2014	Robert Newton
Clean Slate DL01.img	21.7 kB	05/07/2014	Robert Newton
Clean Slate UL02.img	21.7 kB	05/07/2014	Robert Newton