

## CHIRP - Bug # 1937

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Gary Takis	<b>Category:</b>	
<b>Created:</b>	09/25/2014	<b>Assignee:</b>	
<b>Updated:</b>	06/25/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Alinco DR-06		
<b>Platform:</b>	All		
<b>Subject:</b>	DR-06 programming issue		
<b>Description</b>			
<p>Dan,</p> <p>While programming an Alinco DR-06, I tried to load a frequency that gave me a error pop-up that states "Error setting memory: Tuning step 100.00 not supported".</p> <p>For example, when I try and enter KJ7IY's repeater (Sandy) freq of 53.35 the program give me the error window and changes the tune step from 5.0 to to 100.0</p> <p>It also does it on:</p> <ul style="list-style-type: none"><li>53.11 KD7YPY - Mt Hebo</li><li>53.57 W7SIX - Capital Peak</li><li>53.19 K7HW - Olympia</li><li>53.33 N7OEP - Baldi Mtn (Enumclaw)</li><li>53.23 k7pag - Olalla</li></ul> <p>and the list goes on...</p> <p>Other than this quirk, it works great.</p> <p>73 Gary K7GJT</p>			
<b>Related issues:</b>			
duplicates Bug # 1539: Error setting memory: Tuning step 100.00 not supported		<b>New</b>	<b>04/06/2014</b>

### History

#### #1 - 05/01/2020 12:54 pm - Bernhard Hailer

- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from DR-06 to Alinco DR-06
- Platform changed from Windows to All

Is this still an issue with recent versions of Chirp?

#### #2 - 06/25/2020 05:55 pm - Bernhard Hailer

- Status changed from New to Closed

Duplicates #1539. Please follow and post there. Thanks!