

CHIRP - Bug # 2041

Status:	Feedback	Priority:	Normal
Author:	stan malec	Category:	
Created:	11/10/2014	Assignee:	
Updated:	07/13/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-82		
Platform:	Windows		
Subject:	Squelch		
Description			
CHIRP daily-20141025			
Firmware in Radio 82 is b82S25			
When I upload to Radio VHF works fine but the Squelch carrier level changes from .2 uvolts to 1 uvolts well the setting still reads (1)			
I have three radios they all do the same thing when i reset the VFO and punch in frequencies and remeasure it is back to normal			
If I turn off the COS and use pl tone I can hear signals in the noise like I should but the Carrier squelch is rather useless with starting set at 1 u microvolt			

History

#1 - 07/13/2020 05:50 pm - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily
- Model affected changed from Baofeng 82 to Baofeng UV-82

This ticket has been opened a long time ago. Did you try a newer Chirp version?