

CHIRP - Bug # 2145

Status:	New	Priority:	Normal
Author:	Jim Vachalek	Category:	
Created:	12/29/2014	Assignee:	
Updated:	01/02/2015	Due date:	
Chirp Version:	0.4.0		
Model affected:	Wouxon KG-UV8D		
Platform:	Linux		
Subject:	Wouxon KG-UV8D Mode and Power		
Description			
<p>The Mode and power columns can be edited and saved, but when re-opening the file have returned to the previous settings. When writing to the radio they are NFM and L. When reading from the radio they appear to be random, not what is in the radio.</p> <p>CHIRP Version Linux Daily Build 20140924. Radio is Sain Sonic Firmware UVDV1.05, 20140924</p>			

History

#1 - 01/02/2015 12:14 pm - chris d

This also affects the Windows version. Using Daily Build 20150102 Radio is KG-UV8D with Sain Sonic UV8DV1.05 20141013 firmware