

CHIRP - Bug # 2191

Status:	Rejected	Priority:	Normal
Author:	Pete Pon	Category:	
Created:	01/13/2015	Assignee:	
Updated:	01/14/2015	Due date:	
Chirp Version:	daily		
Model affected:	Wouxun KG-UVD8		
Platform:	MacOS		
Subject:	Wouxun KG-UV8D multiple line errors after reading after successful write		
Description	<p>Daily builds 20150102 and 20150104, authentic prolific chipset used. After importing ch settings from another trcvr image and successfully saving and writing to the UV8D, a download produces multiple lines with ERROR. Manually editing the loc and and name and setting the offset and power and returning to the DTCS no error. If edits are done in order by column an error that cross tone is not supported. Secondary issue is that while CHIRP is open there are no errors in the saved image. Upon closing and reopening CHIRP and the saved image the errors reoccur. Issue seems to come up when DTCS is set.</p>		
Related issues:	duplicates Bug # 2143: Wouxun KG-UV8D Memory 54 Closed 12/29/2014		

History

#1 - 01/14/2015 12:58 am - Filippi Marco

- Status changed from New to Rejected

This is a duplicate of #2143

Please look at it and provide the requested info for me to fix it.

Tnx

73 de IZ3GME Marco