

CHIRP - Bug # 2717

Status:	Rejected	Priority:	Normal
Author:	ruí pedro	Category:	
Created:	07/13/2015	Assignee:	
Updated:	07/13/2015	Due date:	
Chirp Version:	0.4.0		
Model affected:	BF-F8+		
Platform:	Windows		
Subject:	Import radio definition		
Description			
<p>Hello, when I try to import the channel list in the CHIRP gives me the error "RADIO refused to send block 0x0000".</p> <p>My radio is a BAOFENG BF-F8+, in the program I'm using the UV-5R in the model.</p> <p>Grateful for your help.</p> <p>Ruí Pedro</p>			

History

#1 - 07/13/2015 03:38 am - ruí pedro

The radio firmware is: BFB297

#2 - 07/13/2015 05:24 pm - Jim Unroe

- Status changed from New to Rejected

Ruí,

The latest Baofeng radios are not compatible with the now over 1 year old CHIRP v0.4.x stable build. You must use a recent CHIRP daily build with these radios.

Jim KC9HI