

CHIRP - New Model # 2853

Status:	Feedback	Priority:	Normal
Author:	Mark Banks	Category:	
Created:	09/16/2015	Assignee:	
Updated:	09/17/2015	Due date:	
Chirp Version:	0.4.0		
Equipment Loan Offered:	No		
Subject:	Baofeng UV-5X		
Description	Cannot read the new UV-5X with any of the read model options. Returns vary		

History

#1 - 09/16/2015 12:08 pm - Mark Banks

Further info: Firmware is at BFB297 and Baofeng VIP s/w does read and write this model.

#2 - 09/16/2015 01:01 pm - Mark Banks

After a read / write with VIP, I am able to use Chirp on these UV-5X radios. Odd and perhaps a hdw issue on my end ? Not sure but a reset didn't replicate the error I was seeing. This can probably be closed ?

#3 - 09/16/2015 06:52 pm - Jim Unroe

- Status changed from New to Feedback

Mark,

Do not use the 17 month old CHIRP v0.4.x stable build. There have been many new models and issues that have required daily builds to address.

Jim KC9HI

#4 - 09/17/2015 07:54 am - Mark Banks

Wrong version was listed in original issue report. This was with 0.4.1. Sorry...

#5 - 09/17/2015 06:51 pm - Jim Unroe

Mark,

The CHIRP v0.4.1 stable build is 17 months old. It was released way before the UV-5X was ever though about. For CHIRP support of the UV-5X you must upgrade to a recent [CHIRP daily build](#). I'm sorry I wasn't more clear in the above reply.

Jim KC9HI