

## CHIRP - New Model # 3235

<b>Status:</b>	Feedback	<b>Priority:</b>	Normal
<b>Author:</b>	Robert Young	<b>Category:</b>	
<b>Created:</b>	01/27/2016	<b>Assignee:</b>	
<b>Updated:</b>	01/27/2016	<b>Due date:</b>	
<b>Chirp Version:</b>	0.4.0		
<b>Equipment Loan Offered:</b>	Yes		
<b>Subject:</b>	Luiton LT-825UV		
<b>Description</b>	<p>New dual band radio that the programming program doesn't work 80% if you are lucky. There are many radios that are exactly the same baofeng has one, sainsonic gt-890, tokmate td-8900, juentai jt-6188, btech mini uv-2501 are all the same radio</p>		
<b>Related issues:</b>	duplicated by New Model # 3237: Luiton LT-825UV		
		<b>Rejected</b>	<b>01/27/2016</b> <b>02/26/2016</b>

### History

#### #1 - 01/27/2016 12:30 am - Robert Young

Disregard

#### #2 - 01/27/2016 12:57 pm - Robert Young

need help with this i still cant get the original program to work contact me if you would like to use my radio, programming cable and software that came with it.

#### #3 - 01/27/2016 01:55 pm - Jim Unroe

- Status changed from New to Feedback

This looks a variant of the QYT KT-8900 which would make this a duplicate of an existing issue. Please follow issue #2673 to track the progress.

If you are running Windows and your programming cable has a Prolific type chip, the chip is most likely counterfeit and the device driver that is automatically installed by Windows is intentionally incompatible.

You will have to download, install and select an older (2007), but compatible, Prolific driver (v3.2.0.0 for Vista and later). Check the [Drivers and USB Cables](#) page of [Miklor.com](#) for a link to the driver and a guide.