

## CHIRP - Bug # 3507

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Jason Fellingham	<b>Category:</b>	
<b>Created:</b>	03/22/2016	<b>Assignee:</b>	Pavel Milanes
<b>Updated:</b>	09/01/2016	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	BTECH UV-5001		
<b>Platform:</b>	Windows		
<b>Subject:</b>	UV-5001 // No response in the write of block #0x0930		
<b>Description</b>			
Error During Write: No response in the write of block #0x0930			
Pretty sure this happens when I am multitasking during the write process.			

### History

#### #1 - 03/23/2016 07:51 am - Pavel Milanes

Hi Jason,

That appears to be just a timing issue, please click on my name link to see my email address and drop me one to send you a modified version of the driver for you to test it.

73 CO7WT.

#### #2 - 04/14/2016 02:01 pm - Pavel Milanes

- Status changed from New to In Progress
- Assignee changed from Jim Unroe to Pavel Milanes
- Priority changed from High to Normal
- % Done changed from 0 to 100

Jason, I'm pretty sure this issue is solved with the recent Chirp version.

Can you confirm this for us to close this thread?

73 CO7WT Pavel.

#### #3 - 06/14/2016 09:12 am - Pavel Milanes

- Status changed from In Progress to Resolved

As no feedback is given I assume that the problem was solved, if not please report back.

Otherwise this issue will be closed in a few days.

73 Pavel CO7WT.

#4 - 09/01/2016 12:26 pm - Pavel Milanes

- Status changed from Resolved to Closed

No user feedback in 3 months and no complains, so I assumed it's safe to close it by now.

#### Files

---

debug.log	3.1 MB	03/22/2016	Jason Fellingham
-----------	--------	------------	------------------