

CHIRP - Bug # 4481

Status:	Closed	Priority:	Normal
Author:	g c	Category:	
Created:	02/02/2017	Assignee:	
Updated:	04/18/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-3R mark II		
Platform:	MacOS		
Subject:	UV-3R mark II		
Description			
<p>"An error has occurred" : "Radio did not ACK first command" try to "Download from Radio"</p> <p>I'm using mac os , I was able to program my Baofeng UV5R5.</p> <p>t.u.</p>			

History

#1 - 02/02/2017 01:53 pm - g c

- File debug.log added

This is my log

#2 - 02/07/2020 11:51 am - Bernhard Hailer

- Status changed from New to Feedback
- Priority changed from Immediate to Normal
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Platform changed from Windows to MacOS

Have you been able to resolve this on your own since you submitted this?

It looks like a cable issue. Please refer to these Wiki articles:

[[CableGuide]]

[[CableGuide FTDI OEM Cables]]

[[RTSystemsCablesAndMavericks]] (if you're running MacOS).

#3 - 02/07/2020 11:52 am - Bernhard Hailer

- Model affected changed from (All models) to Baofeng UV-3R mark II

#4 - 04/18/2020 10:46 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.

Files

debug.log

123 kB

02/02/2017

g c