

CHIRP - Bug # 4587

Status:	Feedback	Priority:	High
Author:	RANDY CAMILOTES	Category:	
Created:	03/06/2017	Assignee:	
Updated:	03/08/2017	Due date:	
Chirp Version:	0.4.0		
Model affected:	Baofeng UV-6R		
Platform:	Windows		
Subject:	Baofeng UV-6R Programming Issue		
Description			
<p>I am programming my Baofeng UV-6R using CHIRP.</p> <p>The following issues have arise:</p> <ol style="list-style-type: none">1. "Name" characters are limited to 6 compared to 7 with UV-5R2. Power-On message does not change after programming3. Cloning progress is incomplete			

History

#1 - 03/08/2017 06:39 pm - Jim Unroe

- Status changed from New to Feedback

| 1. "Name" characters are limited to 6 compared to 7 with UV-5R

This is a limitation of the radio, not CHIRP.

| 2. Power-On message does not change after programming

This is related to #3. The progress doesn't go far enough to write the new power-on messages.

| 3. Cloning progress is incomplete

Include the debug.log file and image file.

Jim KC9HI

Files

BUG.xlsx	824.6 kB	03/06/2017	RANDY CAMILOTES
----------	----------	------------	-----------------