

## CHIRP - New Model # 4669

<b>Status:</b>	Feedback	<b>Priority:</b>	Normal
<b>Author:</b>	Ole Martin Jansen	<b>Category:</b>	
<b>Created:</b>	03/25/2017	<b>Assignee:</b>	
<b>Updated:</b>	09/05/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Equipment Loan Offered:</b>	No		
<b>Subject:</b>	Wouxun KG-819, KG-829		
<b>Description</b>	Why is this radios not supported?		

### History

#### #1 - 09/05/2020 09:49 pm - Bernhard Hailer

- Tracker changed from Bug to New Model
- Subject changed from Wouxun kg-819 and wouxun kg-829 to Wouxun KG-819, KG-829
- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Equipment Loan Offered set to No

The addition of a new radio to Chirp requires two things:

- 1) a volunteer developer who takes the task to work on this driver,
- 2) availability of test equipment, such as a loaner radio (see [\[\[Rules For Loaning A Radio\]\]](#)).

Unfortunately, you need to wait until both conditions have been met.

Or, you could decide to get your hands dirty yourself - check Wiki, "[\[\[Developers\]\]](#)".