

CHIRP - Bug # 5019

Status:	Closed	Priority:	Normal
Author:	Scouter Donn	Category:	
Created:	07/16/2017	Assignee:	
Updated:	05/01/2020	Due date:	
Chirp Version:	daily		
Model affected:	Leixen VV-898E		
Platform:	Windows		
Subject:	VV-898E channel reading		
Description			
<p>As a new user to CHIRP on many of my radios I have come across a bug when reading from my Leixen VV-898E radios. I initially used the factory software to program about 40 channels and it worked fine. However when I switched to using CHIRP it reads the radio but the channels are off, like it only read the odd number channels. When I reprogrammed the radio using the CHIRP and uploaded it my radio only sees the odd channels on bank-a and I think even on bank-b?</p> <p>Am I doing something wrong? I know, I know I am expecting more from a cheap import radio but I am on a budget for my scouts, LOL!</p>			

History

#1 - 03/02/2020 03:54 pm - Bernhard Hailer

- Target version set to chirp-daily
- Model affected changed from VV-898E to Leixen VV-898E

Could you please provide a debug log as described in the Wiki: [\[\[How To Report Issues\]\]](#)? Thanks!

#2 - 05/01/2020 08:07 pm - Bernhard Hailer

- Status changed from New to Closed

No more feedback by submitter.