

CHIRP - Bug # 5205

Status:	Closed	Priority:	Normal
Author:	Lawrence Kraft	Category:	
Created:	09/29/2017	Assignee:	
Updated:	09/09/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-3R+		
Platform:	Windows		
Subject:	Baofeng UV-3R+ decimal in wrong place		
Description	<p>When upload frequencies to my new uv3R+ the offset decimal point is in the wrong place. instead of 00.600 it's 60.000 I have 2 new radios that do this and 2 older ones that upload just fine.</p>		
Related issues:	duplicates Bug # 4635: Baofeng UV-3R Plus Repeater Offset Error		Feedback 03/16/2017

History

#1 - 03/03/2020 01:36 pm - Bernhard Hailer

- Subject changed from Baofeng uv-30R+ to Baofeng UV-3R+ decimal in wrong place
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Baofeng UV-3R+

#2 - 09/09/2020 03:35 pm - Bernhard Hailer

- Status changed from New to Closed

Duplicates #4635. Please follow and post there.