

## CHIRP - Bug # 5217

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Doug Gerard	<b>Category:</b>	
<b>Created:</b>	10/01/2017	<b>Assignee:</b>	
<b>Updated:</b>	02/10/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Baofeng / Pofung UV-6R		
<b>Platform:</b>	Windows		
<b>Subject:</b>	Welcome message not able to be changed and radio image not recognized, UV-6R		
<b>Description</b>			
<p>New UV-6R and prior BFF8+ experience with Chirp for years. The new UV-6R is being used with the 20170714 version. One issue I've noted is that when opening a saved image, I get prompted that it is not for a recognized radio and have to pick the uv-6r from a drop down list. I'm told to let you know if this works ok, and it does.</p> <p>The other issue is that the power on message can't be changed to anything other than "welcome". No other issue noted. Some changes compared to my bff8+, such as the squelch mod does not have uhf settings in addition to the vhf settings. I assume this is no longer necessary. Cloning to the radio seems to proceed fine all the way to completion.</p> <p>Doug NP2GG</p>			
<b>Related issues:</b>			
related to Bug # 4633: UV-6R Incomplete Cloning Progress		<b>Closed</b>	<b>03/16/2017</b>
related to Bug # 5341: Baofeng UV-6R unable to detect model		<b>Closed</b>	<b>11/13/2017</b>
duplicates Bug # 6369: Pofung UV-6R Other Settings and Service Settings		<b>Closed</b>	<b>01/13/2019</b>

### History

**#1 - 02/10/2020 04:33 pm - Bernhard Hailer**

- Status changed from New to Closed

- Model affected changed from UV-6R to Baofeng / Pofung UV-6R

Ticket closed; #6369 has an explanation why this problem persists.