

## CHIRP - Bug # 5401

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Anthony Taveras	<b>Category:</b>	
<b>Created:</b>	11/29/2017	<b>Assignee:</b>	
<b>Updated:</b>	09/09/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Leixen VV-898 V. 107		
<b>Platform:</b>	All		
<b>Subject:</b>	Leixen VV-898 v.107 program / offset issue		
<b>Description</b>			
On the Leixen VV-898 V.107 changes do not appear to be uploading to the radio. when entering a rx frequency the tx offset does not auto-populate			
<b>Related issues:</b>			
related to Bug # 4069: Memories upload to unexpected locations on Leixen VV-898S		<b>In Progress</b>	<b>09/25/2016</b>

### History

#### #1 - 09/09/2020 05:48 pm - Bernhard Hailer

- Status changed from New to Closed
- Priority changed from High to Normal
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Platform changed from Windows to All

Duplicates #4069. Please follow and post there. Thanks!