

CHIRP - Bug # 5513

Status:	Rejected	Priority:	Normal
Author:	Daniel Curry	Category:	
Created:	01/22/2018	Assignee:	
Updated:	01/26/2018	Due date:	
Chirp Version:	daily		
Model affected:	ft1d		
Platform:	Windows		
Subject:	Yaesu FT1DR		
Description			
After upgrading the firmware (3.01) and ptools (4.01). Chirp no longer connect to download configuration. Before the firmware upgrade chip had no issues.			
Related issues:			
duplicates Bug # 5139: Issues with new FT1D/FT1XD Firmware		Feedback	09/10/2017

History

#1 - 01/26/2018 06:03 am - Wade Simmons

- Status changed from New to Rejected

This issue is already being tracked as #5139