

CHIRP - Bug # 5589

Status:	Closed	Priority:	Normal
Author:	TJ Ogilvie	Category:	
Created:	02/17/2018	Assignee:	
Updated:	03/04/2020	Due date:	
Chirp Version:	daily		
Model affected:	Icom IC-208H		
Platform:	Windows		
Subject:	Icom IC-208H Unexpected Response From Radio		
Description			
<p>I am trying to use CHIRP with an Icom IC-208H and am getting an error back of "Clone failed: Failed to communicate with the radio: Unexpected response from radio"</p> <p>Running on Windows 10, and have tried two commercial USB cables and one homemade RS-232 cable with a USB adapter, same result on each cable.</p> <p>Thank you very much!</p>			

History

#1 - 02/17/2018 09:16 am - TJ Ogilvie

I jumped to gun on this, tried a fourth cable, and it is working great with the IC-208H. Please feel free to close this issue.

Thanks

#2 - 03/04/2020 05:01 pm - Bernhard Hailer

- Status changed from New to Closed
- Target version set to chirp-daily
- Model affected changed from IC-208H to Icom IC-208H

Resolved by submitter.

Files

debug.log-Attempt1-208H	30.4 kB	02/17/2018	TJ Ogilvie
debug.log-Attempt2-208H	26.5 kB	02/17/2018	TJ Ogilvie