

CHIRP - Bug # 5645

Status:	Closed	Priority:	Normal
Author:	Michael OBrien	Category:	
Created:	03/15/2018	Assignee:	
Updated:	05/09/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng BF-F8HP, UV-5R		
Platform:	Windows		
Subject:	Baofeng BF-F8HP (UV-5R 3rd Gen) won't program		
Description			
<p>I checked device manager and I have a FTDI cable and am unable to program my radios (I have 3 identical radios purchased together).</p> <p>I am using the latest daily build of CHIRP.</p> <p>I have tried selecting BF-F8HP and UV-5R and with both I get "An error has occurred. Radio refused to send block"</p> <p>I have tried different computers, different USB ports, etc.</p>			

History

#1 - 03/19/2018 04:24 am - Michael OBrien

I went back and checked my order and the cable is the official cable sold by Baofeng (The \$20.46 one).

#2 - 03/06/2020 11:23 am - Bernhard Hailer

- Status changed from New to Feedback
- Target version set to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from (All models) to Baofeng BF-F8HP, UV-5R

Have you been able to resolve this on your own since you submitted this?

Have you tried with a recent version since you submitted this?

If you haven't, and if you're still having this issue, please refer to the Wiki "[[How To Report Issues]]" and provide a debug log. Thanks!

This might still be a cable issue. Please refer to these Wiki articles:

[[CableGuide]]

[[CableGuide FTDI OEM Cables]]

[[RTSystemsCablesAndMavericks]] (if you're running MacOS)

#3 - 05/09/2020 07:35 pm - Bernhard Hailer

- Status changed from Feedback to Closed

No more feedback by submitter.