

CHIRP - Feature # 6307

Status:	Closed	Priority:	Normal
Author:	george TOM	Category:	
Created:	12/16/2018	Assignee:	
Updated:	03/04/2020	Due date:	
Chirp Version:	daily		
Model affected:	QYT KT7900D		
Subject:	CRT-279UV clone QYT KT7900D		
Description	model CRT 279 (clone of QYT KT7900D) MCU-version : VC 5302 Would like a "service settings" menu to allow the squelch thresholds to be adjusted (idem Baofeng UV5R)		

History

#1 - 12/16/2018 09:06 pm - george TOM

RADIO DID NOT ENTER CLONE MODE !!

#2 - 02/11/2020 12:13 pm - Bernhard Hailer

- Status changed from New to Feedback
- Priority changed from High to Normal
- Target version changed from 0.4.1 to chirp-daily

Two things.

- 1) Please try with a recent build of Chirp.
- 2) If if you're still having this issue, please refer to the Wiki [\[\[How To Report Issues\]\]](#) and provide a debug log. Thanks!

#3 - 02/28/2020 12:40 pm - Bernhard Hailer

- Tracker changed from New Model to Bug
- Description updated
- Model affected set to QYT KT7900D
- Platform set to Windows

(This is a bug report, not a New Model request.)

#4 - 02/28/2020 12:41 pm - Bernhard Hailer

- Tracker changed from Bug to Feature

Actually it's a feature request :-)

#5 - 03/04/2020 10:35 am - Bernhard Hailer

- Status changed from Feedback to Closed

Duplicates #6211. Please leave further feedback there. Thanks!