

CHIRP - Bug # 6437

Status:	Closed	Priority:	Normal
Author:	David Elkins	Category:	
Created:	02/11/2019	Assignee:	
Updated:	01/27/2020	Due date:	
Chirp Version:	daily		
Model affected:	UV-50x3		
Platform:	Windows		
Subject:	UV-50x3 programming		
Description			
<p>After setting the frequency > Tone mode DTCS > DTCS code 131 > DTCS rx code 131 > DTCS pol NN > duplex + > offset 5.000000 and mode FM. The DTCS rx code reverts to 23.</p> <p>When I program my UV5R it works fine.</p> <p>I need to use this radio for an upcoming Preparedness drill. Please help....</p>			
Related issues:			
duplicates Bug # 6431: BTech UV-50x3 programming		Closed	02/08/2019

History

#1 - 01/27/2020 02:11 pm - Bernhard Hailer

- Status changed from New to Closed
- Priority changed from Urgent to Normal
- Target version changed from 0.5.0 to chirp-daily

Duplicates #6431.