

## CHIRP - Bug # 6471

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Bruno Bedard	<b>Category:</b>	
<b>Created:</b>	02/18/2019	<b>Assignee:</b>	
<b>Updated:</b>	05/12/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Baofeng BF-F8HP		
<b>Platform:</b>	Windows		
<b>Subject:</b>	Baofeng BF-F8HP - Error setting memory when changing an entry after downloading from radio		
<b>Description</b>			
I get error "Error setting memory: Frequency requires 12.50kHz step" when trying to modify a value on the entry.			
<b>Related issues:</b>			
duplicates Bug # 6469: New software does not support 12.50 error message		<b>Closed</b>	<b>02/17/2019</b>

### History

#### #1 - 02/18/2019 07:39 am - Dan Smith

- Status changed from New to Feedback

Please provide the version you're testing. The version released this morning (20180218) should have fixed this already.

#### #2 - 05/12/2020 08:53 pm - Bernhard Hailer

- Status changed from Feedback to Closed

- Target version set to chirp-daily

- Model affected changed from (All models) to Baofeng BF-F8HP

No more feedback by submitter.