

CHIRP - Bug # 6523

Status:	Resolved	Priority:	Normal
Author:	Tom Hayward	Category:	
Created:	03/02/2019	Assignee:	Tom Hayward
Updated:	03/02/2019	Due date:	
Chirp Version:	daily		
Model affected:	Leixen		
Platform:	All		
Subject:	Fix Leixen valid tuning steps		
Description			
The Leixen driver inherits the Chirp default valid_tuning_steps list instead of setting it correctly for these radios.			

Associated revisions

Revision 3183:c869c5cfc623 - 03/02/2019 08:46 am - Tom Hayward

[leixen] Fix valid_tuning_steps list. #6523

History
