

CHIRP - Bug # 6551

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	03/03/2019	Assignee:	Jim Unroe
Updated:	03/04/2019	Due date:	
Chirp Version:	daily		
Model affected:	Retevis RT21		
Platform:	All		
Subject:	Fix Retevis RT21 valid tuning steps		
Description	The Retevis RT21 driver inherits the Chirp default valid_tuning_steps list instead of setting it correctly for these radios.		

Associated revisions

Revision 3190:418677575e36 - 03/03/2019 10:56 pm - Jim Unroe

[Retevis RT21] fix valid_tuning_steps list. #6551

History

#1 - 03/04/2019 06:24 pm - Jim Unroe

- Status changed from New to Closed

- % Done changed from 0 to 100