

## CHIRP - Bug # 6555

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Jim Unroe	<b>Category:</b>	
<b>Created:</b>	03/03/2019	<b>Assignee:</b>	Jim Unroe
<b>Updated:</b>	03/04/2019	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Retevis RT23		
<b>Platform:</b>	All		
<b>Subject:</b>	Fix Retevis RT23 valid tuning steps		
<b>Description</b>	The Retevis RT23 driver inherits the Chirp default valid_tuning_steps list instead of setting it correctly for these radios.		

### Associated revisions

Revision 3192:5cb3777b71c2 - 03/03/2019 11:37 pm - Jim Unroe

[Retevis RT23] fix valid\_tuning\_steps list. #6555

### History

#1 - 03/04/2019 06:25 pm - Jim Unroe

- Status changed from New to Closed

- % Done changed from 0 to 100