

CHIRP - Bug # 6557

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	03/03/2019	Assignee:	Jim Unroe
Updated:	03/04/2019	Due date:	
Chirp Version:	daily		
Model affected:	Retevis RT26		
Platform:	All		
Subject:	Fix Retevis RT26 valid tuning steps		
Description	The Retevis RT26 driver inherits the Chirp default valid_tuning_steps list instead of setting it correctly for these radios.		

Associated revisions

Revision 3193:1159312ca8d2 - 03/03/2019 11:53 pm - Jim Unroe

[Retevis RT26] fix valid_tuning_steps list. #6557

History

#1 - 03/04/2019 06:26 pm - Jim Unroe

- Status changed from New to Rejected

- % Done changed from 0 to 100

#2 - 03/04/2019 06:28 pm - Jim Unroe

- Status changed from Rejected to Closed