

CHIRP - Bug # 6673

Status:	Closed	Priority:	Normal
Author:	Jeff Lane	Category:	
Created:	04/08/2019	Assignee:	
Updated:	05/14/2020	Due date:	
Chirp Version:	daily		
Model affected:	Icom ID-800H		
Platform:	Windows		
Subject:	Traceback while trying to clone Icom ID-800H		
Description			
<p>I'm not able to download the current settings from my ID-800H, which is supposed to be a supported radio. The only clue other than a generic error box that has no real useful output is this also not terribly helpful traceback:</p>			
<pre>ERROR: ----- /Users/bladernr/Desktop/chirp-daily-20190321.app/Contents/Resources/chirp/chirp/ui/mainapp.py:506: PangoWarning: couldn't load font ".SF NS Text Bold Not-Rotated 14.3994140625", falling back to "Sans Bold Not-Rotated 14.3994140625", expect ugly output. d.run() ERROR: -- Exception: -- ERROR: Traceback (most recent call last): File "/Users/bladernr/Desktop/chirp-daily-20190321.app/Contents/Resources/chirp/chirp/ui/clone.py", line 256, in run self.__radio.sync_in() File "/Users/bladernr/Desktop/chirp-daily-20190321.app/Contents/Resources/chirp/chirp/drivers/icf.py", line 620, in sync_in self._mmap = clone_from_radio(self) File "/Users/bladernr/Desktop/chirp-daily-20190321.app/Contents/Resources/chirp/chirp/drivers/icf.py", line 290, in clone_from_radio raise errors.RadioError("Failed to communicate with the radio: %s" % e) RadioError: Failed to communicate with the radio: Unexpected response from radio ERROR: ----- ERROR: Clone failed: Failed to communicate with the radio: Unexpected response from radio ERROR: --- Exception Dialog: Failed to communicate with the radio: Unexpected response from radio --- ERROR: None ERROR: ----- This is using a cable that DOES work for other Icom radios.</pre>			
Related issues:			
duplicates Bug # 2277: download from ID-880H results in "unexpected response ...		Feedback	01/31/2015

History

#1 - 05/14/2020 12:45 pm - Bernhard Hailer

- Status changed from New to Closed
- Priority changed from Immediate to Normal
- Target version set to chirp-daily
- Model affected changed from ID-800h to Icom ID-800H

Duplicates #2277. Please follow and post there. Thanks!