

## CHIRP - Bug # 6735

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Jim Unroe	<b>Category:</b>	
<b>Created:</b>	04/20/2019	<b>Assignee:</b>	Jim Unroe
<b>Updated:</b>	02/18/2021	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	BJ-218		
<b>Platform:</b>	All		
<b>Subject:</b>	Fix Baojie BJ-218 valid tuning steps		
<b>Description</b>	The Baojie BJ-218 driver inherits the Chirp default valid_tuning_steps list instead of setting it correctly for these radios.		

### Associated revisions

Revision 3225:2ad6dc187df9 - 04/20/2019 03:16 pm - Jim Unroe

[BJ-218] fix valid tuning steps list. #6735

Fixes the following radio models...

Luiton LT725UV

Baojie BJ-218

Hesenate BJ-218

Zastone BJ-218

### History

#1 - 04/20/2019 08:35 am - Jim Unroe

- % Done changed from 0 to 100

Patch submitted

#2 - 04/21/2019 07:44 am - Jim Unroe

- Status changed from New to Feedback

The patch, once accepted, will correct the following Vendor/Models:

Luiton LT725UV

Baojie BJ-218

Hesenate BJ-218

Zastone BJ-218

Jim KC9HI

#3 - 04/24/2019 02:17 am - Jim Unroe

- Status changed from Feedback to Closed

In CHIRP daily build.

**#4 - 02/18/2021 01:07 pm - ADILSON MATOS**

Help!

I have a Zastone radio, the Z218. So, I am trying to use the Chip in the programming, but I am not getting that it is not reading the Radio.

**#5 - 02/18/2021 04:33 pm - Bernhard Hailer**

Adilson, please be advised that this ticket is not about the issue you have. Plus you asked the same already on another unrelated ticket. Best idea would actually be to ask on the [mailing list](#) instead.