

CHIRP - Bug # 6789

Status:	Closed	Priority:	Normal
Author:	Juan Mariano MARTIN	Category:	
Created:	05/14/2019	Assignee:	
Updated:	02/18/2020	Due date:	
Chirp Version:	daily		
Model affected:	Baofeng UV-5R		
Platform:	Windows		
Subject:	BAOFENG UV5R		
Description			
<p>I have programed a UV5R, whit an img dated in 01-20-2019 but the equipmento dos not tx in vhf, sadly i didnot backup the reading of the uv5r, just upload the old img of previous programming.</p> <p>The uv5r works fine in all features, but no tx in vhf, uhf tx ok.</p> <p>lhave reserched all over the web and i can not find a solucion to this problem.</p> <p>The firmware version on the UV5R is HN5RV01 1FB297, and i coul not find an .img to restore it.</p> <p>I wait for yor response.</p> <p>Regards Juan MARTIN</p>			

History

#1 - 05/26/2019 05:34 am - Jim Unroe

- Status changed from New to Feedback
- Assignee deleted (Jim Unroe)

Hi Juan,

Every radio given to me with HN5RV01 firmware has always had some issue with the "factory" image that I grabbed. Scrambled bits here and there or some other obvious issue that made me uncomfortable to share the images publicly. On the occasions that I have shared one of these images with someone trying to solve an unusual issue, the uploaded image has never cured the problem.

I'm sorry, but there is nothing I can do to help you.

Jim KC9HI

#2 - 02/18/2020 06:03 pm - Bernhard Hailer

- Status changed from Feedback to Closed
- Model affected changed from uv5r to Baofeng UV-5R

No more traffic on this ticket.

Files

firmveruv5r.jpg	140.6 kB	05/14/2019	Juan Mariano MARTIN
chinfo.jpg	122.8 kB	05/14/2019	Juan Mariano MARTIN

