

CHIRP - Bug # 7217

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	11/08/2019	Assignee:	Jim Unroe
Updated:	11/17/2019	Due date:	
Chirp Version:	daily		
Model affected:	[UV-82]		
Platform:	All		
Subject:	Incorrect detection of UV-82 series CHIRP Radio Images (*.img) files		
Description	<p>Old Baofeng UV-82 series (UV-82, UV-82C, UV-82HP, UV-82L, UV-82X, etc) CHIRP Radio Images (*.img) files that do not have the "metadata blob trailer" are incorrectly detected as being from a Radioddity UV-82X3.</p>		

Associated revisions

Revision 3261:067b69c9b7d0 - 11/09/2019 01:33 am - Jim Unroe

[UV-82] Fix for incorrect detection of old UV-82 series images

Old CHIRP Radio Images (*.img) from Baofeng UV-82 series radio models that do not have a "metadata blob trailer" are incorrectly detected as being from a Radioddity UV-82X3.

This patch separates the UV-82X3 into a separate "basetype" to address this issue.

#7217

History

#1 - 11/17/2019 06:47 pm - Jim Unroe

- Status changed from *New* to *Resolved*
- % Done changed from 0 to 100

fix is in current daily builds.

Jim KC9HI

#2 - 11/17/2019 06:47 pm - Jim Unroe

- Status changed from *Resolved* to *Closed*