

## CHIRP - Bug # 8091

<b>Status:</b>	Closed	<b>Priority:</b>	Normal
<b>Author:</b>	Lee Martinez	<b>Category:</b>	
<b>Created:</b>	07/17/2020	<b>Assignee:</b>	
<b>Updated:</b>	10/05/2020	<b>Due date:</b>	
<b>Chirp Version:</b>	daily		
<b>Model affected:</b>	Baofeng UV-82C		
<b>Platform:</b>	Windows		
<b>Subject:</b>	DSL code for baofeng not in chirp		
<b>Description</b>			
<p>Hello</p> <p>I have a GMRS V1 and a UV-82C. I am trying to program these for use with a repeater. The repeater uses split tones for TX and RX. I need code D155N - code 028. I also need code D255N code 045.</p> <p>In the drop downs for the DCS field I have 045, but not 028. I only have 026 and the next is 031.</p> <p>Why is this? How can I program D155N without te 028 drop down?</p> <p>Missinaz</p>			

### History

---

**#1 - 07/18/2020 07:16 am - Jim Unroe**

- Status changed from New to Feedback

You should take some time to read [Understanding CHIRP's Columns](#). But here is how you would set it up...

Tone Mode: Cross

Cross Mode: DTCS->DTCS

DTCS Code: 155

DTCS Rx Code: 255

DTCS Pol: NN

For questions on how to use CHIRP you should ask on the [chirp\_users] mailing list.

Jim KC9HI

**#2 - 10/05/2020 04:44 pm - Bernhard Hailer**

- Status changed from Feedback to Closed

- Priority changed from Urgent to Normal

Answers provided.