

CHIRP - Bug # 8613

| | | | |
|--------------------------------------------------------------|---------------------------------------|------------------|-----------|
| Status: | Closed | Priority: | Normal |
| Author: | Jim Unroe | Category: | |
| Created: | 12/31/2020 | Assignee: | Jim Unroe |
| Updated: | 01/08/2021 | Due date: | |
| Chirp Version: | daily | | |
| Model affected: | (All models) | | |
| Platform: | All | | |
| Subject: | Driver Maintenance: baofeng_common.py | | |
| Description | | | |
| 1. Add to PEP8 manifest 2. Perform PEP8 cleanup as needed | | | |

Associated revisions

Revision 3449:726f1b1bdae0 - 01/01/2021 02:26 am - Jim Unroe

Driver Maintenance: baofeng_common.py

1. Add to PEP8 manifest
2. Perform PEP8 cleanup

fixes #8613

History

#1 - 12/31/2020 06:29 pm - Jim Unroe

- Status changed from *In Progress* to *Resolved*

- % Done changed from 0 to 100

patch submitted

Jim KC9HI

#2 - 01/08/2021 04:45 pm - Anonymous

- Status changed from *Resolved* to *Closed*

Applied in changeset commit:726f1b1bdae0.