

CHIRP - Bug # 9859

Status:	Resolved	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	05/07/2022	Assignee:	Jim Unroe
Updated:	05/07/2022	Due date:	
Chirp Version:	daily		
Model affected:	MURS-V1		
Platform:	All		
Subject:	MURS-V1: check limit for PTT-LT setting is incorrect.		
Description			
<p>The setting range for PTT-LT is 0-50. The MURS-V1 driver currently forces values above 30 down to the factory default value of 5. The upper check limit should be 50.</p> <p>Jim KC9HI</p>			

History

#1 - 05/07/2022 09:55 pm - Jim Unroe

- Status changed from *In Progress* to *Resolved*
- % Done changed from 0 to 100

Patch submitted.

Jim KC9HI