

CHIRP - Bug # 9995

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	08/21/2022	Assignee:	Jim Unroe
Updated:	08/23/2022	Due date:	
Chirp Version:	daily		
Model affected:	RT29		
Platform:	All		
Subject:	[RT29] Transmit Power Levels Not Set Correctly		
Description	When programming the Retevis RT29_UHF or Retevis RT29_VHF, the Power setting is not read or written correctly. Jim KC9HI		

Associated revisions

Revision 3729:7b0f58ad7899 - 08/23/2022 12:29 am - Jim Unroe

[RT29] Power Levels are Incorrectly Applied

This patch corrects the faulty operation of the Power setting for the Retevis RT29_UHF and RT29_VHF radios.

fixes #9995

History

#1 - 08/21/2022 10:00 pm - Jim Unroe

- Status changed from *In Progress* to *Resolved*
- % Done changed from 0 to 100

A patch has been submitted. Support will be in the next CHIRP daily build following acceptance.

Jim KC9HI

#2 - 08/23/2022 12:53 am - Anonymous

- Status changed from *Resolved* to *Closed*

Applied in changeset commit:7b0f58ad7899.