

CHIRP - Bug # 10034

Status:	Feedback	Priority:	Normal
Author:	Timothy Gillespie	Category:	
Created:	09/12/2022	Assignee:	
Updated:	09/12/2022	Due date:	
Chirp Version:	daily		
Model affected:	Icom IC-80AD		
Platform:	Linux		
Subject:	IC-80AD		
Description			
<p>although its listed as supported The IC-80AD is not listed in download from list, tried detect but get error getting radio model, also tried the IC-91/92AD. It started download from radio but there was zero data and this radio has been programed with some vhf/uhf and D-Star data. I am running the latest Chirp at this time 20220911</p>			

History

#1 - 09/12/2022 10:20 pm - Jim Unroe

- Status changed from New to Feedback

After searching the CHIRP bug tracker for IC-80AD there have been a handful of issues opened where this model is the one being programmed. Looking at a one of the debug.log files that was submitted, it is clear that the submitter is selecting IC-80H to program their IC-80AD radio.

If this doesn't work, do you have access to a Windows computer where you can try the ICOM cloning software to verify that the programming cable works correctly with your radio?

I hope this helps.

Jim KC9HI