

CHIRP - Bug # 1637

Status:	New	Priority:	Normal
Author:	Jens Jensen	Category:	
Created:	05/16/2014	Assignee:	Jens Jensen
Updated:	05/16/2014	Due date:	
Chirp Version:	0.4.0		
Model affected:	TM-271a		
Platform:	All		
Subject:	[TM-271] missing tuning steps		
Description	TM-271a missing tuning steps		

History

#1 - 05/16/2014 11:41 am - Jens Jensen

- File *kenwood_live.py* added

please try the attached

Files

kenwood_live.py	39.7 kB	05/16/2014	Jens Jensen
-----------------	---------	------------	-------------