

CHIRP - Bug # 1977

Status:	Closed	Priority:	Normal
Author:	Jim Unroe	Category:	
Created:	10/16/2014	Assignee:	Jim Unroe
Updated:	11/11/2014	Due date:	
Chirp Version:	daily		
Model affected:	[UV-5R]		
Platform:	Windows		
Subject:	[UV-5R] Update pre_download and pre_upload Messages		
Description			
<p>Some recently shipping Baofeng UV-5R variants require the volume control to be at 100% for reliable data transfer. Update the pre_download and pre_upload messages accordingly.</p>			

Associated revisions

Revision 2273:aa0152be3d90 - 10/16/2014 05:52 pm - Jim Unroe

[UV-5R] Update pre_download And pre_upload Messages

Update the pre_download and pre_upload messages to advise that it is sometimes necessary to have the volume control at 100% for reliable data transfer.

related to #1977

History

#1 - 11/11/2014 02:48 am - Filippi Marco

- Status changed from New to Closed