

CHIRP - Bug # 2145

Status:	Feedback	Priority:	Normal
Author:	Jim Vachalek	Category:	
Created:	12/29/2014	Assignee:	
Updated:	04/26/2020	Due date:	
Chirp Version:	daily		
Model affected:	Wouxun KG-UV8D		
Platform:	Linux		
Subject:	Wouxun KG-UV8D Mode and Power		
Description			
<p>The Mode and power columns can be edited and saved, but when re-opening the file have returned to the previous settings. When writing to the radio they are NFM and L. When reading from the radio they appear to be random, not what is in the radio.</p> <p>CHIRP Version Linux Daily Build 20140924. Radio is Sain Sonic Firmware UVDV1.05, 20140924</p>			
Related issues:			
related to Bug # 5483: Wouxun UV-8D download with DCS receive filter always on		New	01/06/2018

History

#1 - 01/02/2015 12:14 pm - chris d

This also affects the Windows version. Using Daily Build 20150102 Radio is KG-UV8D with Sain Sonic UV8DV1.05 20141013 firmware

#2 - 04/26/2020 05:58 pm - Bernhard Hailer

- Subject changed from Wouxun KG-UV8D Mode and Power to Wouxun KG-UV8D Mode and Power
- Status changed from New to Feedback
- Target version changed from 0.4.1 to chirp-daily
- Chirp Version changed from 0.4.0 to daily
- Model affected changed from Wouxun KG-UV8D to Wouxun KG-UV8D

Have you tried with a recent version since you submitted this? Thanks!