

CHIRP - Bug # 2225

| | | | |
|------------------------|--|------------------|-----|
| Status: | Feedback | Priority: | Low |
| Author: | Matthew Davies | Category: | |
| Created: | 01/19/2015 | Assignee: | |
| Updated: | 01/19/2015 | Due date: | |
| Chirp Version: | daily | | |
| Model affected: | (All models) | | |
| Platform: | Windows | | |
| Subject: | Squelch mod related bug. Both BF-E500S and UV5R+Plus ignore new squelch settings yet remember them. | | |
| Description | <p>Tried the new mod (Thanks for that BTW.) on my BF-E500S and UV5R+Plus. With the PL off and on the same band neither radio obeys the new settings. If I change the settings with CHIRP, even down to 1, and upload it to the radio and reset it the radio acts like I didn't change anything but if I download the settings/freq file it says I did. It remembers. If I set the radio to squelch slot zero the squelch opens. If I program slot one to zero nothing changes. Squelch stays closed. Firmware BFB297.</p> <p>So, both radios ignore the new settings yet they remember them.</p> | | |

History

#1 - 01/19/2015 03:23 pm - Jim Unroe

- Status changed from New to Feedback

Mathew,

Squelch 0 can only be set to 0 (everything else is ignored).

Squelch 1 - 9 can only be set to 1 - 64 (0 is ignored).

This is the way the radio works. CHIRP cannot change it.

Jim KC9HI