

CHIRP - Bug # 2397

Status:	New	Priority:	Normal
Author:	Dennis Gibson	Category:	
Created:	03/08/2015	Assignee:	
Updated:	03/08/2015	Due date:	
Chirp Version:	0.4.0		
Model affected:	(pofung uv-5r		
Platform:	Windows		
Subject:	file		
Description			
<p>When you bring down radio drop down and enter info port # for radio, radio type and try to connect error comes back cannot find file. also windows 8 installs driver info from usb cable but but will not work.</p>			

History
